

Mechanics, getting serviceable parts is essential to keeping your aircraft mission ready.

Check your back shops for the ARC-231 receiver transmitter, NSN 5821-01-500-4770, and the KAB mount, NSN 5975-01-555-9367. If you have these parts in your area, turn them in **now** through normal supply channels.

Here's where you turn in the parts:

Receiver Transmitter 1808A
NSN 5821-01-500-4770
SV3114
DLA Distribution
Tobyhanna
Spec Handling FAC PH 570 615 7354
Building 13 6th Street
Tobyhanna PA 18466



ARC-231 receiver transmitter

KAB Mount

NSN 5975-01-555-9367

DODDAAC: W25G1W

RIC: BY6

W1A8 DLA Distribution

Tobyhanna

Marked for B16 stock, Condition Code:

Gibbs and Fifth Streets

Warehouse 6 Bay 4

Tobyhanna PA, 18466-5059



KAB mount

Remember, it's also important to turn in unserviceable equipment because unserviceable return credit for parts is back on! Not doing so leads to low serviceable stock supply, critical supply system shortages and longer wait times for other units to receive serviceable equipment. Then readiness takes a hit.

Got questions? Email the item manager, Christopher Doolittle, at:

christopher.m.doolittle3.civ@army.mil