


Composite Main Rotor Blades, Swash Plates, and MUMT B17 Items

Composite Main Rotor Blades, Tail Rotor Swash Plates and MUMT requirements need to be ordered through the standard GCSS-Army business process after May 1 2019 due to the transition off PBL. Please ensure all excess assets (serviceable or unserviceable) for CMRBs and Swash plates are turned in to the SSA or shipped to Plant 7011 (AQ5). All B17 CL IX MUMT assets (excluding Rovers) need to be shipped to Tobyhanna (plant 7000 RIC BY6). Rovers need to be returned to Tobyhanna (Plant 7119 RIC SCY). If you have questions concerning any of the items below, please contact the Item Manager listed.




Composite Main Rotor Blade
Item Manager Rayanna Jowers
rayanna.a.jowers.civ@army.mil



Material: 015995169, PN: 7-511527038-105 & 016308902, PN: 7-511527038-107,

Swash Plate

Item Manager Cortez Morris,
alby.c.morris.civ@army.mil



Material: 015995172, PN: 7-311511101-25 & 016131790, PN: 7-511511101-101,

Main Rotor Swash Plate

Item Manager Cortez Morris,
alby.c.morris.civ@army.mil