



**THE
PREVENTIVE
MAINTENANCE
MONTHLY
INDEX**

TB 43-PS-835

**15
AUGUST
2023**

Of Online Articles

<https://www.psmagazine.army.mil>





The Preventive Maintenance Monthly Index of Online Articles

Issue 835

General & Special Topics	2
Aviation	5
CBRN	8
Combat Vehicles	10
Construction	12
Commo/Electronics	14
H2F	16
Logistics/Maintenance Management	18
Medical Logistics	20
Mines	22
Missiles	24
Small Arms	26
Soldier Support	28
Tactical Vehicles	30
Tools	32

TB 43-PS-835, **The Preventive Maintenance Monthly Index of Online Articles** is an official publication of the Department of the Army, providing a reference tool for all Soldiers assigned to combat and combat support units to access PS Magazine articles published to its official .mil website. All referenced articles have been reviewed and approved by the agency responsible for the equipment, publication or policy discussed in any referenced article. Application of the information in those articles is encouraged but optional with the user. The use of product or company names does not constitute endorsement of those products, services or companies by the U.S. Army. The use of non-DoD hyperlinks, along with that content, does not constitute endorsement by the DoD or DA. Neither DoD nor DA exercises any editorial control over, and cannot vouch for, content on non-DoD websites.

PS: The Preventive Maintenance Monthly Index of Online Articles (ISSN 0475-2953)
is published monthly by the Department of the Army, Redstone Arsenal, AL 35898.

You are invited to send PS your ideas for improving maintenance procedures, questions on maintenance and supply problems and questions or comments on material published in PS.

Just write to:

MSG Half-Mast
PS, the Preventive Maintenance Monthly
USAMC ARMY SUSTAINMENT COMMAND
BLDG 3218 Snooper Rd.
Redstone Arsenal, AL 35898

Or email:

usarmy.redstone.asc.mbx.psmag@army.mil

Internet address:

<https://www.psmagazine.army.mil>

By Order of the Secretary of the Army:

JAMES C. MCCONVILLE
General, United States Army
Chief of Staff

Official:

MARK F. AVERILL
Administrative Assistant
to the Secretary of the Army

2320852

DISTRIBUTION:
Distributed in electronic media only (EMO).

General and Special Topics



Date	Article Title	Link	Excerpt
6-Jul-23	I Sustain This: June 2023 Nominees	https://www.psmagazine.army.mil/News/Article/3449470/i-sustain-this-june-2023-nominees/	PS Magazine's I Sustain This campaign is designed to recognize civilian sustainers who exemplify the highest standards while maintaining equipment to meet combat readiness requirements and stay in the fight, even under the most arduous of circumstances. For June 2023, we had one civilian sustainer nominated for this program. Read on to learn about the nominee and their contributions to Army readiness...
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
10-Jul-23	Heat Safety: Army's Annual Guidance Worth the Read	https://www.psmagazine.army.mil/News/Article/3452510/heat-safety-armys-annual-guidance-worth-the-read/	Stay alert for the signs of heat-related illnesses with the Army's annual guidance. Learn more here...
11-Jul-23	SINCGARS: Searching for PMCS Tables	https://www.psmagazine.army.mil/News/Article/3454892/sincgars-searching-for-pmcs-tables/	A Soldier is asking about where to locate the PMCS tables for SINCGARS. Half-Mast has the answer. It's available in a TM covering over 20 models. To find out more, read on...
17-Jul-23	Apache: Correctly Reinstall Generator Wires	https://www.psmagazine.army.mil/News/Article/3460087/apache-correctly-reinstall-generator-wires/	This article initially appeared in PS 594 (02), p. 39. When removing generator wires, make sure you use heat-shrinkable bands to help you reinstall the wires correctly after maintenance. Read on to find out more...


19-Jul-23

Ground Vehicles:
6TAGM MILSPEC
Batteries Can be
Mixed

<https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/>

PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...

Aviation



Date	Article Title	Link	Excerpt
6-Jul-23	Publications: Update Pubs Account Address	https://www.psmagazine.army.mil/News/Article/3449003/publications-update-pubs-account-address/	Change your pubs account address to reflect the new Army base installation name changes to receive publications.
6-Jul-23	UH-60: Install Wire Jumper Kits ASAP	https://www.psmagazine.army.mil/News/Article/3448794/uh-60-install-wire-jumper-kits-asap/	All Black Hawk aircraft units need to install the wire jumper kits by Feb 2024 per AMAM 22-09.
6-Jul-23	Apache: Color of Grease Not Cause for Gearbox Replacement	https://www.psmagazine.army.mil/News/Article/3448719/apache-color-of-grease-not-cause-for-gearbox-replacement/	Grease discoloration in the Apache tail rotor gearbox and intermediate gearbox is not sufficient cause for replacing them.
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	This "corrosion basics" slide presentation offers a template for corrosion training.
11-Jul-23	Apache: Servocylinders Critically Needed	https://www.psmagazine.army.mil/News/Article/3454228/apache-servocylinders-critically-needed/	Turn in unserviceable Apache servocylinders, NSN 1650-01-494-0084, ASAP to support repair program.
13-Jul-23	MEDEVAC: Discharge Cable Helps with Static Electricity	https://www.psmagazine.army.mil/News/Article/3456297/medevac-discharge-cable-helps-with-static-electricity/	Using a static discharge cable during MEDEVAC hoist operations can lessen the negative effects of static electricity.

13-Jul-23	Aviation Maintenance: MOS 15B Invited to Take Job Analysis Survey	https://www.psmagazine.army.mil/News/Article/3457514/aviation-maintenance-mos-15b-invited-to-take-job-analysis-survey/	All MOS 15Bs should take the job analysis survey at the link below.
17-Jul-23	Black Hawk: Use Proper Pliers	https://www.psmagazine.army.mil/News/Article/3460648/black-hawk-use-proper-pliers/	Use cannon plug pliers to remove the load-demand and the power-available rotary input housing.
17-Jul-23	Apache: Correctly Reinstall Generator Wires	https://www.psmagazine.army.mil/News/Article/3460087/apache-correctly-reinstall-generator-wires/	Make sure Apache generator wire leads are marked properly so they can be reinstalled correctly after maintenance to prevent frying generators.
21-Jul-23	H-60 Series: Keep Struts Lubed	https://www.psmagazine.army.mil/News/Article/3466629/h-60-series-keep-struts-lubed/	Landing gear struts and the stabilator actuator rod should be lubed every 40 hours to prevent landing gear problems.
25-Jul-23	Apache: Generator is Heavier Than You Think	https://www.psmagazine.army.mil/News/Article/3470342/apache-generator-is-heavier-than-you-think/	.The Apache generator is heavy so always use tool kit, NSN 5180-01-508-5887 when installing or removing the generator.
28-Jul-23	All Aircraft: Pay Attention to TM Warnings, Cautions and Notes	https://www.psmagazine.army.mil/News/Article/3474566/all-aircraft-pay-attention-to-tm-warnings-cautions-and-notes/	Warnings, cautions and notes in every TM keep you safe while performing maintenance so read them and heed them

CBRN




Date	Article Title	Link	Excerpt
10-Jul-23	M12A1 Decon: New Mixing Instructions for JGPD-HME	https://www.psmagazine.army.mil/News/Article/3452686/m12a1-decon-new-mixing-instructions-for-jgpd-hme/	The M12A1 decontaminating apparatus has new mixing instructions for JGPD-HME M333 decontamination kit. You can get the complete instructions on the JACKS website. Keep reading for more...
10-Jul-23	M26 Decon: New Throttle Lever Modification	https://www.psmagazine.army.mil/News/Article/3452795/m26-decon-new-throttle-lever-modification/	If you have a new M26 throttle lever, NSN 3040-12-371-3949, it will need to be modified before use. The throttle lever assembly orientation is incorrect so the lever assembly must be disassembled to make the necessary modifications. Keep reading for the instructions...

Combat Vehicles



Date	Article Title	Link	Excerpt
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
11-Jul-23	Bradley FOV: Properly Dispose of Fuel After Checking for Contamination	https://www.psmagazine.army.mil/News/Article/3454484/bradley-fov-properly-dispose-of-fuel-after-checking-for-contamination/	Don't put fuel drained from the Bradley fuel filter used to test for contamination back into the fuel tank, even if not contaminated. Read on for more info...
18-Jul-23	M1-Series Tank: Turn In Unserviceable LRUs ASAP	https://www.psmagazine.army.mil/News/Article/3461656/m1-series-tank-turn-in-unserviceable-lrus-asap/	Units can get turn-in credit and improve combat readiness by turning in line replaceable units (LRUs) for the M1-series tank. Not turning in unserviceable LRUs can cause supply issues. Read on for more info...
18-Jul-23	Ground Vehicles: Don't Get Mixed Up with Batteries	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	While it's recommended to use the same NSN batteries in vehicles requiring multiple batteries, it's not recommended to mix old and new batteries. Keep reading to find out why...
19-Jul-23	Bradley FOV: Check Towing Pintle Regularly for Damage	https://www.psmagazine.army.mil/News/Article/3463300/bradley-fov-check-towing-pintle-regularly-for-damage/	Checking the towing pintle for signs of damage is a regular part of maintenance. Read on for more info...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...

Construction



Date	Article Title	Link	Excerpt
6-Jul-23	BEB: BII Hand Pump	https://www.psmagazine.army.mil/News/Article/3449832/beb-bii-hand-pump/	Excess water in the bridge boat's hull can cause problems, but there's a remedy among the basic issue items. Read on to find out what it is...
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
18-Jul-23	Ground Vehicles: Don't Get Mixed Up with Batteries	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	While it's recommended to use the same NSN batteries in vehicles requiring multiple batteries, it's not recommended to mix old and new batteries. Keep reading to find out why...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
24-Jul-23	M917A3 Heavy Dump Truck: Helpful Reminders during Dumping Ops	https://www.psmagazine.army.mil/News/Article/3468685/m917a3-heavy-dump-truck-helpful-reminders-during-dumping-ops/	Maintenance leaders, operating the M917A3 30-ton heavy dump truck is challenging. Here's a few key reminders when dropping dirt or gravel with your heavy dump truck. Get them here...

Commo/Electronics




Date	Article Title	Link	Excerpt
6-Jul-23	VOSS: Recycle Old or Used Desiccators	https://www.psmagazine.army.mil/News/Article/3448716/voss-recycle-old-or-used-desiccators/	Find out how to inspect or replace the desiccator in the VOSS gimbal, NSN 5855-01-626-6338. WP 0030 in TM 5-5895-1984-10 (Oct 16) shows you how....
6-Jul-23	OGS: TM Updated	https://www.psmagazine.army.mil/News/Article/3449562/ogs-tm-updated/	An updated TM has been published for the operational intelligence ground station (OGS). Learn more here...
11-Jul-23	SINCGARS: Searching for PMCS Tables	https://www.psmagazine.army.mil/News/Article/3454892/sincgars-searching-for-pmcs-tables/	A Soldier is asking about where to locate the PMCS tables for SINCGARS. Half-Mast has the answer. It's available in a TM covering over 20 models. To find out more, read on...
26-Jul-23	NVGs: Order the Correct Army Helmet Mount	https://www.psmagazine.army.mil/News/Article/3471961/nvgs-order-the-correct-army-helmet-mount/	When it comes to Army NVG helmet mounts for the NVGs AN/PVS-7 and NVG AN/PVS-14, only one NSN is approved. Learn more here...

H2F



There are no new articles this month.

Logistics Management



Date	Article Title	Link	Excerpt
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...

Medical Logistics




There are no new articles this month.

Mines




Date	Article Title	Link	Excerpt
5-Jul-23	AN/PSS 14C Mine Detector: Get a Grip on the Grip	https://www.psmagazine.army.mil/News/Article/3447397/anpss-14c-mine-detector-get-a-grip-on-the-grip/	The AN/PSS 14C mine detector handle is made of plastic, so handle it with care. Use the forearm strap when operating the mine detector, to reduce the chance of damage. Read on for more tips to keep the detector detecting...
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...

Missiles



Date	Article Title	Link	Excerpt
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
10-Jul-23	Avenger: Remote Control Unit with VIC-5	https://www.psmagazine.army.mil/News/Article/3452594/avenger-remote-control-unit-with-vic-5/	Avenger has new remote control units (RCUs) available for the VIC-5 with a permanent dual operator system bracket. There are two models, each with its own NSN and part number. Read on for more...
18-Jul-23	Ground Vehicles: Don't Get Mixed Up with Batteries	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	While it's recommended to use the same NSN batteries in vehicles requiring multiple batteries, it's not recommended to mix old and new batteries. Keep reading to find out why...
19-Jul-23	Avenger: New Canopy Covers Now Available	https://www.psmagazine.army.mil/News/Article/3462616/avenger-new-canopy-covers-now-available/	There are newly designed canopy covers for the Avenger. They come in tan or green. Keep reading to get the NSNs...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
24-Jul-23	Avenger: New Bar Type Cable Clamp	https://www.psmagazine.army.mil/News/Article/3462544/avenger-new-bar-type-cable-clamp/	The Avenger has a new style cable clamp. You can get it with NSN 5342-01-116-7949, PN BACC10DS5. Keep reading for more...

Small Arms



Date	Article Title	Link	Excerpt
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...

Soldier Support




Date	Article Title	Link	Excerpt
10-Jul-23	Heat Safety: Army's Annual Guidance Worth the Read	https://www.psmagazine.army.mil/News/Article/3452510/heat-safety-armys-annual-guidance-worth-the-read/	Stay alert for the signs of heat-related illnesses with the Army's annual guidance. Learn more here....

Tactical Vehicles



Date	Article Title	Link	Excerpt
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
18-Jul-23	Ground Vehicles: Don't Get Mixed Up with Batteries	https://www.psmagazine.army.mil/News/Article/3462391/ground-vehicles-dont-get-mixed-up-with-batteries/	While it's recommended to use the same NSN batteries in vehicles requiring multiple batteries, it's not recommended to mix old and new batteries. Keep reading to find out why...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...
28-Jul-23	Wheeled Vehicles: One Stop Shop for Tire & Wheel Assemblies	https://www.psmagazine.army.mil/News/Article/2481765/wheeled-vehicles-one-stop-shop-for-tire-wheel-assemblies/	This article was updated 7/28/2023. Soldiers, before you go tire shopping, there's something you need to keep in mind. Ordering a replacement tire is not authorized when a tire and wheel assembly NSN exists. Read on for more information...

Tools



Date	Article Title	Link	Excerpt
7-Jul-23	Corrosion: Training the Basics	https://www.psmagazine.army.mil/News/Article/3450929/corrosion-training-the-basics/	Maintenance leaders, PS has an excellent PowerPoint presentation that you can download and use to train Soldiers on basic corrosion information or tailor to your equipment and vehicles. Read on...
19-Jul-23	Ground Vehicles: 6TAGM MILSPEC Batteries Can be Mixed	https://www.psmagazine.army.mil/News/Article/3464028/ground-vehicles-6tagm-milspec-batteries-can-be-mixed/	PulseTech® Products Corporation recently released the U.S. Army Battery Maintenance Management Program (BMMP) (May 23). The BMMP describes the three batteries that you could receive with NSN 6140-01-485-1472, and they're authorized to be mixed. Read more...

This page left intentionally blank

Make **PMCS**...

WOULD YOU STAKE
YOUR LIFE, *RIGHT NOW*,
ON THE CONDITION OF
YOUR EQUIPMENT?



...a **Team Effort** in your **Motor Pool!**